



Engine Protection Partner AS

Schaller Automation Scandinavia & Baltics

-OUR KNOWLEDGE IS YOUR SAFETY-



Gasket for inspection cover 10166/355336

Name of component:	Gasket for inspection cover
Old part no.:	10166
New part no.:	355336
For model:	All VN/87

Export data:

Material:	Rubber
Country of origin:	DE
HS code:	90 3190 00
Dimensions (cm):	14,55x5,9x0,2
Net weight (g):	22